


Restoration and Meadow Emergence



Phase IIIB
Reach 1
2010-2012

Phase I
2003

Phase II
2006

Phase IIIA
Reach 6
2008-09

89

Lake Tahoe

- Dirt Road
- Paved Road
- Blackwood Cr Watershed




1.5 Miles



History 1939 - Reach 6 Aerial Photo

A little narrow stream wandering through a cottonwood forest...

DFG 1934-38 "a wonderful stream for spawning in normal winters having good natural propagation, containing beautiful pools, continuous shade and shelter




Year	Channel Length (m)	Sinuosity
1939	985	1.80
1969	894	1.63
1986	835	1.53
1995	777	1.42
2001	731	1.34
2007	674	1.23

History - 2007 Reach 6 Aerial Photo

Little or none of the old stream left...or floodplain...



Year	Channel Length (m)	Sinuosity
1939	985	1.80
1969	894	1.63
1986	835	1.53
1995	777	1.42
2001	731	1.34
2007	674	1.23



2010 post construction



2011 post construction



2016 post construction



2015 Emerging meadow area downstream of a roughness structure



Oak Creek – a meadow that once was (sort of)

